# Raytown Water Co.

## Computerized Leak Detection Survey 10/20/23

Cost Analysis

This survey was conducted by Westrum Leak Detection utilizing the latest leak detection correlation technology to pinpoint suspected leakage in the system. The following leaks were located.

Leak Chart is \$1 per 1,000 gallons lost

	No. of Leaks	GPD (per leak)	Millions per year	Dollars per year
Main leaks	6	6,000	13.14	\$13,140
Abandoned leaks	0	0	0	\$0
Service line leaks	5	3,500	6.3875	\$6,388
Valve leaks	3	4,000	4.38	\$4,380
Hydrant leaks	5	500	0.9125	\$913
Total	19	14,000	24.82	\$24,820




Estimated payback period in weeks:	14
Leak cost per week:	\$477
Survey Cost	\$6,500.00

As you know, because of increased production and test and maintenance costs, operation and maintaining an efficient water distribution system has become a necessity. The most effective method to reach and maintain that goal is with an annual leak detection program. We appreciate the opportunity to serve you.

WESTRUM LEAK		515-838-2222 (24-7) 888-500-4433 (24-7)	Cell 515-231-0122
--------------	--	--	-------------------

Manhole O	Ra	aytown Wa	ter Co.	
Hydrant ¥ Valve <b>X</b>	Survey	Service	Date - 10/20/23	}
<b></b>				




### **Westrum Leak Detection**

3226 360th St Stratford, IA 50249 1-888-500-4433 - 24/7


North

Date Repair	rea
	)
Operate stop	box

YES NO




				_
Manhole 🔘	D	ovtovno Mot	or Co	
Stop Box	n.	aytown Wat	er co.	
Hydrant 🕌				
lyulant 🌑	Suprov (A)	Service	Date - 10/20/23	
Valve 🔀	Survey 🦲	Service	Date - 10/20/23	_
North				



**Westrum Leak Detection** 

Date R	epaired
Operate	ston hov
Operate	X Stop box
YES	NO

Description of Repair		




3226 360th St Stratford, IA 50249 1-888-500-4433 - 24/7

		_
Operate	stop box	K
	~	

NO

YES

Description of Repair		



Leak Indication


Main leak approximately 85'-90' from hydrant valve A. Leak area is marked in the street.


52nd Terr.

A

Westrum Leak Detection 3226 360th St Stratford, IA 50249 1-888-500-4433 - 24/7

Date Repaired	<b>Description of Repair</b>
Operate stop box	
X	
YES NO	





Westrum Leak Detection 3226 360th St

Stratford, IA 50249 1-888-500-4433 - 24/7

Date i	cepai	rea	2
Onerate	cton	hov	7
Operate	: groh	DUA	


×

NO

Description of Repair		

Manhole O Stop Box	Rayt	own Water	Company
Hydrant 🤘 Valve 🞇	Survey <a> </a>	Service	Date - 10/20/23
<b>A</b>			






#### **Westrum Leak Detection**

Date Repaired	
$\overline{}$	
Operate s	top box

perate	stop box
	×
YES	NO

Description of Repair		

Manhole O	Rayt	own Water	Company
'⊣ydrant <b>४</b> Valve <b>⋈</b>	Survey	Service	Date - 10/20/23
<b>†</b>			




**Westrum Leak Detection** 


3226 360th St Stratford, IA 50249 1-888-500-4433 - 24/7

North

Operate stop box


~
^





Manhole 🔘	Raytown Water Company		
Stop Box	, lay	own water	Company
Hydrant 🔰 Valve 🔀	Survey	Service	Date - 10/20/23
Valve 🔣 l		250 SEAR 10 WESTER	






**Westrum Leak Detection** 

Date Repaired	
Operate s	top box

perate	stop box
	×
YES	NO



Manhole  Stop Box  Hvdrant	Raytown Water Co.	Leak
Hydrant ⊌ Valve 🔣	Survey Service Date - 10/20/23	
North	Leak Indication  Possible valve leaking in this area. There is some indication that there is possibly a valve buried under the asphalt in this area.	
	Cresent	
)	C. G.	
	60th Terr.	

**Westrum Leak Detection** 


Date R	epaired
Operate	stop box
	X
YES	NO

Description of Repair		

Manhole O	Rayt	own Water	Company
Hydrant 🔰	Survey <a> <a> <a> <a> <a> <a> <a> <a> <a> <a></a></a></a></a></a></a></a></a></a></a>	Service	Date - 10/20/23
† North			



Service line leak at or near the corporation tap. This could possibly be a main leak just east of the corporation tap to #9309.



**Westrum Leak Detection** 

3226 360th St Stratford, IA 50249 1-888-500-4433 - 24/7

Date Re	epaired
Operate s	stop box
	X

NO

YES


Description of Rep	air

Manhole O	Raytown Water Company			
'Hydrant    Valve   ▼	Survey Service Date - 10/20/23			
1 North				

13

Leak #

### **Leak Indication**



**Westrum Leak Detection** 

3226 360th St Stratford, IA 50249 1-888-500-4433 - 24/7

Date Repai	rea
	)
Operate stop	box

12507


perate	stop box
	×
YES	NO

Description of Repair		

Manhole 🔵	D	ovtovno Mot	or Co
Stop Box	n.	aytown Wat	er co.
Hydrant 🖌	Cumrasi (a)	Comilee	Data 10/00/00
Valve 🞇	Survey 🦲	Service	Date - 10/20/23
1 North			

### **Leak Indication**

Possible small main leak in this area. There was a small amount of noise on the valve shown.




#### **Westrum Leak Detection**

Date Repaired		
<u> </u>		
Operate stop l	OOX	

perate	stop box
	×
YES	NO


Description of Repair		



Manhole O Stop Box  Hydrant	Raytown Water Co.				
Valve 🔀	Survey Service Date - 10/20/23				
1 North					


## **Leak Indication**

This hydrant is leaking.



10617?

Date Repaired	Description of Repair	_
Operate stop box		
	Operate stop box	Operate stop box



Manhole () Stop Box () 'Hydrant () Valve ()	Raytown Water Co.  Survey Service Date - 10/20/23					
North	Leak Indication  This hydrant is leaking.					
	11408					
( )	Willow					

**Westrum Leak Detection** 


3226 360th St Stratford, IA 50249 1-888-500-4433 - 24/7 Date Repaired
Operate stop box

perate	stop	box
	×	
YES	NO	

Description of Repair

Manhole O	Raytown Water Co.					
ʻlydrant ⊌ Valve 🔣	Survey		Service		Date - 10/20/23	
<b>†</b> North						

ak#



**Westrum Leak Detection** 

3226 360th St Stratford, IA 50249 1-888-500-4433 - 24/7

paired
top box

		1		
perate	stop box			
	×			
YES	NO			

**Description of Repair**